


QUICK START

LKBD/LKBDM



- 1 On/off switch / Display light
- 2 On/off switch sound (signal at 0° and 90°)
- 3 Hold function (measurement is saved by pressing once) / Switching between ABS (absolute) and INC (incremental)
- 4 Mode button for switching between measured value settings (°, mm/m, %, in/ft)
- 5 Arrows show in which direction the spirit level has to be moved
- 6 Display ° / mm/m / % / in/ft
- 7 Display of ABS or INC
- 8 Display in the case of low battery voltage

1 sec. → ON

2 sec. → OFF

1

1 x → 0°; 90°

1 x →

3

1 x →

1 x →

2

1 x →

1 x →

4

KESON LLC

810 N. Commerce Street
Aurora, Illinois 60504
(800) 345-3766

info@keson.com, www.keson.com



Please find the operating instructions on
www.keson.com

R373263XKE

